

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Easterly views of drain inlet adjacent to Orient Avenue.



55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Easterly view of drain pipe outlet on adjacent lot along northern property boundary

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Easterly view of drain pipe outlet (zoomed)

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Westerly view of drain pipe outlet

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Westerly view of drain pipe outlet (zoomed)

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Westerly view of drainage ditch

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Easterly view of drainage ditch

55 Orient Avenue Site Photographs: 2/10/2021 and 3/1/2021



Easterly view of drainage ditch with Phragmites swamp in background